

Mandatory Language for Surface Water Treatment Technique Violation
SURFACE WATER TREATMENT TECHNIQUE

The Texas Commission on Environmental Quality (TCEQ) sets minimum water quality standards for public drinking water. These standards include enforceable treatment technique requirements for drinking water. Inadequately treated water may contain disease-causing organisms. These organisms include bacteria, viruses, and parasites that can cause symptoms such as nausea, cramps, diarrhea, and associated headaches.

The WEBB COUNTY WATER UTILITIES, PWS ID TX2400022, failed to meet the minimum treatment technique requirements for the month of **April 2015**. Specifically, our water system had **failure to provide Cryptosporidium treatment as established under the Long Term 2 Enhanced Surface Water Treatment Rule**.

The Webb County Utilities is in the process of installing a new UV Disinfection System scheduled for completion in September of 2015 to meet these new standards implemented on October 2014. Upon completion of this equipment your treatment plant will be not only complying with new standards but also surpassing standards into 99.999% removal rates.

Please share this information with all people who drink this water, especially those who may not have received this notice directly (i.e., people in apartments, nursing homes, schools, and businesses). You can do this by posting this notice in a public place or distributing copies by hand or mail.

If you have questions regarding this matter, you may contact Adrian Montemayor, Systems Manager at (956) 523-5590.

Posted /Delivered on:

Idioma Obligatorio para Violación de Técnica de Tratamiento de Agua Superficial TÉCNICA DE TRATAMIENTO DE AGUA SUPERFICIAL

La Comisión de Texas Sobre la Calidad Ambiental (TCEQ) establece estándares de calidad de agua mínimo para el agua potable pública. Estos estándares incluyen requisitos de técnica de tratamiento aplicable para agua potable. El Agua tratada inadecuadamente puede contener organismos causantes de enfermedades. Estos organismos incluyen bacterias, virus y parásitos que pueden causar síntomas tales como náuseas, calambres, diarrea y asociados dolores de cabeza.

Las utilidades de agua del Condado de WEBB, PWS ID TX2400022, fallo al cumplir con los requisitos mínimos de la técnica de tratamiento durante el mes de **Abril de 2015**. Específicamente, nuestro sistema de agua fallo en proveer el **tratamiento de Cryptosporidium como es establecido bajo el Largo Plazo 2 Regla de Tratamiento de Agua de Superficie**.

Las Utilidades del Condado de Webb están en proceso de instalar un sistema de desinfección UV nuevo programado para la terminación en Septiembre de 2015 para cumplir con estos nuevos estándares implementados en Octubre de 2014. Al terminar con este equipo su planta de tratamiento no sólo cumplirá con nuevas normas, sino también superara los niveles en las tasas de extracción de 99.999%.

Por favor comparta esta información con todas las personas que beben esta agua, especialmente aquellos que no han recibido este aviso directamente (es decir, personas en apartamentos, hogares de ancianos, escuelas y empresas). Puede hacer esto mediante la publicación de este aviso en un lugar público o distribuir copias a mano o por correo.

Si usted tiene preguntas con respecto a este asunto, puede contactar a Adrian Montemayor, Gerente de sistemas en (956) 523-5590.

Publicada /entregado en: