

RFP 2015-11 Rio Bravo Park Soccer Field Improvements

Addendum #1

July 10, 2015

1. Type of fiber to bid on will be "slit film"
2. Pile weight will be 40 ounces per square yard
3. Backing will be 7.8 to 7.9 ounces per square yard
4. Total weight will be 67.8 to 73.9 ounces
5. Price should include a field brush sweeper at least 3 feet wide
6. Amount of sand/pebble needed will be 3 pounds per square foot; amount of rubber will be 3 pounds per square foot; padding will thus have 6 pounds per square foot with a 50/50 mix
7. The turf will have an 8 pound minimum tough bind
8. Bid will not include a fence
9. Please report the warranty with as much detail as possible
10. A soil sample and Geo Tech information will be provided before the start of the project
11. The base will be caliche base from Martin Marietta Materials
12. The enclosed picture was distributed at the pre proposal meeting of July 9, 2015.
13. No additional time has been added to the RFP due date. RFP is due **July 20, 2015 at 2PM.**

Please sign and date (must be included in the Proposal)



2710 Wycliff Road
 Raleigh, North Carolina 27607
 919-781-4550

MATERIAL SAFETY DATA SHEET

Effective Date: 5-08

Replaces: 6-10-99

I – PRODUCT AND COMPANY IDENTIFICATION		
CHEMICAL NAME Crushed Caliche	CHEMICAL FORMULA Not Applicable	MOLECULAR WEIGHT Not Applicable
TRADE NAME Caliche		
SYNONYMS Base Material, Caliche Base		DOT IDENTIFICATION NO. None

II – COMPOSITION/INFORMATION ON INGREDIENTS				
COMPONENT(S) CHEMICAL NAME	CAS REGISTRY NO	% by weight (approx)	MSHA/OSHA PEL	ACGIH TLV-TWA
Calcium Carbonate (CaCO ₃)	471-34-1	70.5	(T) 15 mg/m ³ , (R) 5 mg/m ³	NA
Quartz (Crystalline silica)*	14808-60-7	28.5	(R) 10 mg/m ³ / (% SiO ₂ +2)†	(R) 0.025 mg/m ³
Silica Dioxide (SiO ₂) (cristobalite) (tridymite)				
Trace elements less than 1%		<1		
*Content of this material varies naturally				

*: The composition of SiO₂ may be up to 100% crystalline silica. (R): Respirable (T): Total ‡: Crystalline silica is normally measured as respirable dust. The OSHA standard also presents a formula for calculation of the PEL based on total dust: 30 mg/m³ / (% SiO₂+2). †: Particulate matter containing no asbestos and <1% crystalline silica.

III – HAZARDS IDENTIFICATION	
Grey cubical rock fragment: 1 inch to dust in size. Odorless	
Health Effects: The information below represents an overview of health effects caused by overexposure to one or more components in crushed caliche. The individual effects are described in Section XI.	
Primary route(s) of exposure:	<input checked="" type="checkbox"/> Inhalation <input type="checkbox"/> Skin <input type="checkbox"/> Ingestion
EYE CONTACT:	Direct contact with dust may cause irritation by mechanical abrasion. Conjunctivitis may occur
SKIN CONTACT:	Direct contact may cause irritation by mechanical abrasion. Some components of material are also known to cause mild corrosive effects to skin and mucous membranes.
SKIN ABSORPTION:	Not expected to be a significant exposure route.

INGESTION: Small amounts (a tablespoonful) swallowed during normal handling operations are not likely to cause injury. Ingestion of large amounts may cause gastrointestinal irritation and blockage.

INHALATION: Dusts may irritate the nose, throat, and respiratory tract by mechanical abrasion or corrosive action. Coughing, sneezing, chest pain, shortness of breath, inflammation of mucous membrane, and flu-like fever may occur following exposures in excess of appropriate exposure limits. Repeated excessive exposure may cause pneumoconiosis, such as silicosis and other respiratory effects.

Silicosis:

Use of Crushed Caliche base for construction purposes is not believed to cause additional acute toxic effects. Repeated overexposures to respirable crystalline silica (quartz, cristobalite, tridymite) for periods as short as 6 months has caused acute silicosis.

Symptoms of acute silicosis include (but are not limited to): shortness of breath, cough, fever, weight loss, and chest pain. Acute silicosis is a rapidly progressive, incurable lung disease and is typically fatal.

Chronic exposure to respirable quartz-containing dust in excess of appropriate exposure limits has caused silicosis, a progressive pneumoconiosis (lung disease). Restrictive and/or obstructive lung function changes may result from chronic exposure.

Lung Cancer:

Crystalline silica is classified by the International Agency For Research on Cancer (IARC) as a carcinogenic to humans (Group 1). Prolonged and repeated breathing of silica may cause lung cancer.

Tuberculosis:

Silicosis increases the risk of Tuberculosis.

Autoimmune and Chronic Kidney Disease:

Some studies show excess number of cases of scleroderma, connective tissue disorders, lupus, rheumatoid arthritis, chronic kidney diseases and end-stage kidney disease in worker exposed to respirable crystalline silica.

Non-Malignant Respiratory Diseases (other than Silicosis):

Some studies show an increased incidence in chronic bronchitis and emphysema in workers exposed to crystalline silica.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

Inhaling respirable dust and/or crystalline silica may aggravate existing respiratory system disease(s) and/or dysfunctions.

Exposure to dust may aggravate existing skin and/or eye conditions. Smoking and obstructive / restrictive lung diseases may also exacerbate the effects of excessive exposure to this product.

IV – FIRST AID MEASURES

EYES: Flush eyes immediately with plenty of fresh water for at least 15 minutes, lifting the lower and upper lids occasionally. Seek medical attention immediately.

SKIN: Wash contaminated skin immediately with soap and water. Remove contaminated clothing at once. Obtain medical attention if irritation persists.

INHALATION: Remove to fresh air. If breathing is difficult, administer oxygen. If breathing has stopped, give artificial respiration. Keep person warm and quiet. **OBTAIN MEDICAL ATTENTION IMMEDIATELY.**

INGESTION: If person is conscious, give a large quantity of water and induce vomiting; however, never attempt to make an unconscious person drink or vomit. Get medical attention.

V – FIRE FIGHTING MEASURES

FLASHPOINT
Non flammable

FLAMMABLE LIMITS IN AIR
Not Applicable

EXTINGUISHING AGENT
None required

UNUSUAL FIRE AND EXPLOSION HAZARD

Contact with powerful oxidizing agents may cause fire and/or explosions (see Section X of this MSDS).

VI – ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Persons involved in cleaning should first follow the precautions defined in Section VII of the MSDS. Spilled materials, where dust can be generated, may overexpose cleanup personnel to respirable quartz-containing dust. Wetting of spilled material and/or use of respiratory protective equipment may be necessary. Do not dry sweep spilled material.

This product is not subject to the reporting requirements of Title III of SARA, 1986, and 40 CFR 372.

VII – HANDLING AND STORAGE

This product is not intended or designed for, and should not be used as an abrasive blasting medium or for foundry applications. Follow protective controls set forth in Section VIII of this MSDS when handling this product.

Respirable quartz-containing dust may be generated during processing, handling and storage. Do not breathe dust.

Avoid contact with skin and eyes.

Do not store near food or beverages or smoking materials.

Do not stand on piles of materials; it may be unstable.

VIII – EXPOSURE CONTROLS/PERSONAL PROTECTION

ENGINEERING CONTROLS

Ventilation: Use only in well ventilated areas.

Other control measures: Respirable dust and quartz levels should be monitored regularly. Dust and quartz levels in excess of appropriate exposure limits should be reduced by all feasible engineering controls, including (but not limited to) dust suppression (wetting), ventilation, process enclosure, and enclosed employee work stations. Local exhaust ventilation should be used to capture dust at source of generation.

EYE/FACE PROTECTION

Safety goggles.

SKIN PROTECTION

Not required

RESPIRATORY PROTECTION

Respirator Recommendations:

For respirable quartz levels that exceed or are likely to exceed appropriate exposure limits, a NIOSH-approved 100 series particulate filter respirator must be worn. If respirable quartz levels exceed or are likely to exceed an 8 hour-TWA of 0.5 mg/m³, a NIOSH-approved air purifying, full-face respirator with a 100 series particulate filter must be worn. Respirator use must comply with applicable MSHA or OSHA standards, which include provisions for a user training program, respirator repair and cleaning, respirator fit testing, and other requirements. For additional information contact NIOSH at 1-800-356-4674.

Emergency or planned entry into unknown concentrations or IDLH conditions: Any self-contained breathing apparatus that has a full-face piece and is operated in a pressure-demand or other positive-pressure mode or any supplied-air respirator that has a full-face piece and is operated in a pressure-demand or other positive-pressure mode in combination with an auxiliary self-contained positive-pressure breathing apparatus.

Escape from unknown or IDLH conditions: Any air-purifying, full-face piece respirator with a high-efficiency particulate filter or any appropriate escape-type, self-contained breathing apparatus.

GENERAL HYGIENE CONSIDERATIONS

Remove dust from exposed skin with soap and water. Wash clothing.

IX – PHYSICAL AND CHEMICAL PROPERTIES

APPEARANCE AND ODOR Grey cubical rock fragment: 1 inch to dust in size. Odorless	SPECIFIC GRAVITY. 2.59
BOILING POINT Not Applicable	VAPOR DENSITY IN AIR (AIR = 1) Not Applicable
VAPOR PRESSURE 0 mm Hg at 20°C	% VOLATILE, BY VOLUME Not Applicable
EVAPORATION RATE Not Applicable	SOLUBILITY IN WATER Not Applicable

X – STABILITY AND REACTIVITY

STABILITY Stable	CONDITIONS TO AVOID None known
INCOMPATIBILITY (Materials to avoid) Acids, alum, ammonium salts, mercury & hydrogen, fluorine, magnesium	
HAZARDOUS DECOMPOSITION PRODUCTS Contact with powerful oxidizing agents such as fluorine, boron trifluoride, chlorine trifluoride, manganese trifluoride, and oxygen difluoride may cause fire and/or explosions. Silica dissolves in hydrofluoric acid producing a corrosive gas- silicon tetra fluoride.	

XI – TOXICOLOGICAL INFORMATION

This product is a mixture of components. The composition percentages are listed in Section II. Toxicological information for each component is listed below:

Calcium Carbonate:

Exposure route: Inhalation, skin/eye contact.

Target organs: Eyes, skin, respiratory system.

Acute effect: Irritation of the eyes, skin and respiratory system and cough. It has been reported that there may be a silicosis risk when using impure limestone containing in excess of 3% quartz. However, it is claimed that pure calcium carbonate does not cause pneumoconiosis. Adverse health effects have generally not been reported in literature among workers using CaCO₃.

Chronic effect/carcinogenicity: Not classifiable as human carcinogen

Silicon Dioxide: In some batches, crystalline silica may represent up to 100% of silicon dioxide.

Respirable crystalline silica (quartz):

ACGIH TLV= 0.025 mg/m³

MSHA and OSHA PEL:

Crystalline quartz (respirable): PEL-TWA 10 mg/m³/ (%SiO₂ + 2).

Crystobalite: Use ½ the value calculated from the count or mass formulae for quartz.

Tridymite: Use ½ the value calculated from the formulae for quartz.

Other Particulates: TLV = 10 mg/m³ (inhalable total particulate, not otherwise classified), TLV = 3 mg/m³ (respirable particulate, not otherwise classified), OSHA PEL = 15 mg/m³ (total particulate, not otherwise regulated), OSHA PEL = 5 mg/m³ (respirable particulate, not otherwise regulated)

ACGIH, MSHA, and OSHA have determined that adverse effects are not likely to occur in the workplace provided exposure levels do not exceed the appropriate exposure limits. Lower exposure limits may be appropriate for some individuals including persons with pre-existing medical conditions such as those described below.

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE

Inhaling respirable dust and/or crystalline silica may aggravate existing respiratory system disease(s) and/or dysfunctions.

Exposure to dust may aggravate existing skin and/or eye conditions.

Occupational exposure to free silica is known to produce silicosis, a chronic, disabling lung disease characterized by the formation of silica-containing nodules of scar tissue in the lungs. Simple silicosis, in which the nodules are less than 1 cm in diameter is generally asymptomatic but can be slowly progressive, even in the absence of continued exposure.

Silicosis leads to conditions such as lung fibrosis and reduced pulmonary function. The form and severity in which silicosis manifests itself depends in part on the type and extent of exposure to silica dusts: chronic, accelerated and acute forms are all recognized. In later stages the critical condition may become disabling and potentially fatal. Restrictive and/or obstructive changes in lung function may occur due to exposure. A risk associated with silicosis is development of pulmonary tuberculosis (silico-tuberculosis). Respiratory insufficiencies due to massive fibrosis and reduced pulmonary function, possibly with accompanying heart failure, are other potential causes of death due to silicosis.

Symptoms of Silicosis: Not all individuals with silicosis will exhibit symptoms (signs) of the disease. However, silicosis is progressive, and symptoms can appear at any time, even years after exposures have ceased. Symptoms of silicosis may include (but are not limited to): Shortness of breath; difficulty breathing with or without exertion; coughing; diminished work capacity; diminished chest expansion; reduction of lung volume; right heart enlargement and/or failure. Persons with silicosis have an increased risk of pulmonary tuberculosis infection.

Respirable dust containing newly broken particles has been shown to be more hazardous to animals in laboratory tests than respirable dust containing older silica particles of similar size. Respirable silica particles which had aged for sixty days or more showed less lung injury in animals than equal exposures of respirable dust containing newly broken pieces of silica.

There are reports in the literature suggesting that excessive crystalline silica exposure may be associated with adverse health effects involving the kidney, scleroderma (thickening of the skin caused by swelling and thickening of fibrous tissue) and other autoimmune disorders. However, this evidence has been obtained primarily from case reports involving individuals working in high exposure situations or those who have already developed silicosis; and therefore, this evidence does not conclusively prove a causal relationship between silica or silicosis and these adverse health effects. Several studies of persons with silicosis also indicate increased risk of developing lung cancer, a risk that increases with the duration of exposure. Many of these studies of silicosis do not account for lung cancer confounders, especially smoking. In October 1996, an IARC Working group re-assessing crystalline silica, a component of this product, designated crystalline silica as carcinogenic (Group 1). The NTP indicates that crystalline silica is reasonably anticipated to be a carcinogen (Group 2). These classifications are based on sufficient evidence of carcinogenicity in certain experimental animals and on selected epidemiological studies of workers exposed to crystalline silica. Crystalline silica in October 1996 was listed on the Safe Drinking Water and Toxic Enforcement ACT of 1986 (California Proposition 65) as a chemical known to the state to cause cancer or reproductive toxicity.

XII – ECOLOGICAL INFORMATION

No data available

XIII – DISPOSAL CONSIDERATIONS**WASTE DISPOSAL METHOD**

Product can be reused. Dispose in a sanitary landfill or approved land recovery site. There is no known state or local agency regulations on the disposal of crushed caliche.

XIV – TRANSPORT INFORMATION**DOT HAZARD CLASSIFICATION**

None

PLACARD REQUIRED

None

LABEL REQUIRED

Label as required by the OSHA Hazard Communication standard (29 CFR 1910.1200(D)), and applicable state and local regulations.

XV – REGULATORY INFORMATION

Crystalline silica, a component of this product, is on the NTP and IARC carcinogen lists, but not on the OSHA carcinogen list. In October 1996, an IARC Working group re-assessing crystalline silica, a component of this product, designated crystalline silica as a human carcinogen (Group 1 carcinogen).

Crystalline silica in October 1996 was listed on the Safe Drinking Water and Toxic Enforcement ACT of 1986 (California Proposition 65) as chemical known to the state to cause cancer or reproductive toxicity.

XVI – OTHER INFORMATION

ACGIH: American Conference of Governmental Industrial Hygienists

C: Ceiling limit; the concentration that should not be exceeded during any part of the working exposure

CFR: US Code of Federal Regulations

DOT: US Department of Transportation

IARC: International Agency for Research on Cancer

IDLH: Immediately Dangerous to Life and Health

NIOSH: National Institute for Occupational Safety and Health, US Department of Health and Human Services

NTP: National Toxicology Program

OSHA: Occupational Safety and Health Administration, US Department of Labor

PEL: Permissible Exposure Limit

SARA Title III: Title III of the Superfund Amendments and Reauthorization Act, 1986

TLV: Threshold Limit Value

TWA: Time-weighted Average

FOR FURTHER INFORMATION	CONTACT:	Martin Marietta Aggregates Manager-Safety 2710 Wycliff Road Raleigh, NC 27607 919/781-4550 HOURS; 8 AM – 5 PM (EST)
DATE OF PREPARATION 5/08		

NOTICE: Martin Marietta Materials believes that the information contained on this Material Safety Data Sheet is accurate. The suggested precautions and recommendations are based on recognized good work practices and experience as of the date of publication. They are not necessarily all-inclusive or fully adequate in every circumstance as not all use circumstances can be anticipated. Also, the suggestions should not be confused with nor followed in violation of applicable laws, regulation, rules or insurance requirement. However, product must not be used in a manner which could result in harm.

NO WARRANTY, EXPRESSED OR IMPLIED, OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR OTHERWISE IS MADE

MSDS 3600-002

Materials

- Sandstone

SANDSTONE											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSLA	RSSM			RSMD	CA-RSAI
							IIMAC	ST	MS		
Capitol Aggregates	Brownlee	1402704	082, 093, 094	029	A	25	17	11	20	15	5
Martin Marietta	Apple (Sawyer, OK)	0050437	082, 093, 094	029	A	15	27	15	15	12	98
Smith Buster Crushed Stone, LLC	Byrd Pit	0050447	093, 094	029	A	33	25	23		13	28

- Limestone-Dolomites

LIMESTONE-DOLOMITES											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSLA	RSSM			RSMD	CA-RSAI
							IIMAC	ST	MS		
Alamo Concrete	Weir	1424603	093, 094	018	B	33	11	25		27	0
Austin Aggregates	Lampasas Quarry	1402706	093, 094	018	B	28	6	5		12	0
Austin Aggregates	Naruna	1402711	093, 094	018	B	28	7	8		12	4
Border Pacific	Matrimar	0040103	093, 094	019	B	26	5	5		12	0
Cedar Creek Stone	Pate	0914710	093, 094	018	B	*39	29	23		29	18
Cemex	Balcones Quarry	1504602	093, 094	018	B	33	13	17		24	0
Cemex	McKelligon-Dolomite	2407201	093, 094	019	B	25	7	7		11	1
Centex Materials	Ruby	1410607	093, 094	018	B	29	16	12		21	0
Colorado Materials	Hunter	1504605	093, 094	018	B	30	21	19		22	1
CSA Materials	Turner	0722611	093, 094	018	B	33	21	16		25	2
Dean Word Co.	Lone Star	1504607	093, 094	018	B	29	15	15		21	0
Dolese Brothers	Ardmore, OK	0050412	093, 094	018	B	27	11	15		15	0

LIMESTONE-DOLOMITES											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSI-A	RSSM			RSMD	CA-RSA1
							HMAC	ST	MS		
Dolese Brothers	Coleman, OK	0050414	093, 094	019	B	23	1	1		10	1
Dolese Brothers	Cooperton, OK	0050415	093, 094	018	B	26	4	5		11	0
Dolese Brothers	Richards Spur	0050405	093, 094	019	B	26	10	10		15	0
H.L. Zumwalt Construction, Inc.	FM 1283 Ranch Quarry	1516317	093, 094	018	B	35	10	23		12	1
Hanson Aggregates	Bridgeport Perch-Hill	0224901	093, 094	018	B	26	8	8		14	0
Hanson Aggregates	Burnet	1402701	093, 094	019	B	27	3	2		9	0
Hanson Aggregates	Servtex	1504603	093, 094	018	B	17	13	17		19	0
Industrial Asphalt & Aggregate	Florence Quarry	1424608	093, 094	018	B	12	21	19		28	0
Industrial Asphalt & Aggregate	Hays Quarry	1410608	093, 094	018	B	11	13	12		20	3
Jobe Materials, L.P.	Ned Finney Quarry	2407220	093, 094	018	B	24	2	2		11	0
Jones Brothers	Rankin	0623102	093, 094	018	B	10	27	24		20	0
Killeen Crushed Stone	Gibbs	0901408	093, 094	018	B	31	12	11		16	0
Lattimore Materials	Stringtown, OK	0050407	093, 094	019	A	21	8	8		1	17
Martin Marietta	Beckmann	1501503	093, 094	018	B	12	18	14		22	0
Martin Marietta	Bridgeport	0224904	093, 094	018	B	27	15	11		18	1
Martin Marietta	Chambers	0224921	093, 094	018	B	10	22	22		21	0
Martin Marietta	I-35 @ Solms Rd	1504606	093, 094	018	B	11	18	19		23	0
Martin Marietta	Mill Creek, OK	0050445	093, 094	018	B	12	1	1		11	2
Martin Marietta	Rio Medina Quarry	1516312	093, 094	018	B	11	12	10		18	0
Oldcastle Materials Texas	Marble Falls Quarry	1402702	093, 094	019	B	29	1	8		11	0
South Texas Aggregates	Chapman	1523211	093, 094	018	B	*40	15	11		11	0
Texas Crushed Stone	Feld	1424602	093, 094	018	B	12	16	12		22	0
Vulcan Materials	1604	1501506	093, 094	018	B	33	21	23		27	0
Vulcan Materials	Brownwood	2302501	093, 094	018	B	24	9	1		15	0
Vulcan Materials	Eastland	2306805	093, 094	018	B	26	14	10		17	0
Vulcan Materials	Helotes	1501514	093, 094	018	B	26	1	7		17	0

LIMESTONE-DOLOMITES											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSLA	RSSM			RSMD	CA-RSAI
							HMAC	ST	MS		
Vulcan Materials	Huebner Rd	1501507	093, 094	018	B	30	23	22		23	0
Vulcan Materials	Mico	1516315	093, 094	018	B	34	14	12		23	1
Vulcan Materials	North Troy	0050448	093, 094	019	B	25	8	11		8	7
Vulcan Materials	Spicewood	1402710	093, 094	019	B	21	6	6		7	0
Vulcan Materials	Tehuacana	0914708	093, 094	018	B	34	13	9		22	11
Vulcan Materials	Weatherford	0218409	093, 094	018	B	27	15	14		17	0
Zack Burkett Co	Leach	0212001	093, 094	018	B	27	13	13		17	0
Zack Burkett Co	Springfield Quarry	0212002	093, 094	018	B	25	12	11		16	8

• Gravels

GRAVELS											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSLA	RSSM			RSMD	CA-RSAI
							HMAC	ST	MS		
Anderson Columbia Co, Inc.	AC Rio Grande Pit	2225301	093, 094	011	A	18	3	2		4	92
Bay, Inc.	Sweet 16	2206706	093, 094	011	A	19	2	1		1	89
Big Creek Construction	Mitchell Pit	0907401	093, 094	024	B	23	5	4		10	37
Big Creek Construction	Young	0907402	093, 094	024	B	22	6	4		1	39
Big Creek Sand & Gravel, Inc.	Big Creek	0411807	093, 094	011	A	21	7	5		1	21
Capitol Aggregates	Hoban	0619502	082, 093, 094	033	A	20	12	11	1	8	98
Colorado Materials	Madison Pit	1523216	093, 094	024	B	22	4	3		8	20
Duininck Brothers	Matador	2517309	083, 094	014	A	27	7	6		8	81

GRAVELS											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSLA	RSSM			RSMD	CA-RSAI
							HMAC	ST	MS		
Fordyce Co.	Murphy	1323505	093, 094	014	A	18	3	11		5	92
Fordyce Co.	Showers	2110904	093, 094	014	A	20	7	6		5	87
Frontera Materials	Reavis	2110906	093, 094	014	A	20	5	4		5	87
Gilvin-Terrill, Ltd.	Fletcher Pit	2506508	093, 094	014	A	35	12	13		13	91
Hanson Aggregates	Little River	0050114	093, 094	011	A	21	11	11		5	99
J. Lee Milligan, Inc.	Archer Pit	2517311	093, 094	014	A	30	10	8		10	82
J. Lee Milligan, Inc.	Aztec Canyon	0418814	093, 094	024	B	22	12	12		15	71
J. Lee Milligan, Inc.	Boys Ranch	0418008	093, 094	011	A	31	7	5		9	91
J. Lee Milligan, Inc.	Frasier Pit	2506509	093, 094	014	A	22	11	7		10	93
J. Lee Milligan, Inc.	Sawyer	0406510	093, 094	014	A	22	12	12		12	87
Jobe Materials, L.P.	Avispa Canyon	2407229	093, 094	021	B	22	7	7		12	1
LS Sand & Gravel	LS Pit	0418002	093, 094	014	A	22	12	11		11	81
Martin Marietta	Broken Bow S & G	0050451	093, 094	011	A	26	13	13		10	98
Mine Service Ltd.	Pit 424	1716611	093, 094	024	B	24	6	6		11	20
R.E. James Gravel Co.	South Noodle	0812803	Partly Crushed	025	B	26	15	14		17	22
South Texas Aggregates	D and D	2215905	093, 094	024	B	25	9	7		12	22
Texas Sand & Gravel	Krister-Fain	0418812	093, 094	014	A	21	12	10		10	74
Thrasher S & G	Thrasher	2517302	093, 094	014	A	28	15	12		12	78
Upper Valley Materials	Las Viboras	2110905	093, 094	014	A	20	12	10		6	78
Valley Caliche	Beck	2110901	093, 094	014	A	23	14	11		8	74
Wright Materials	Realitos	2106701	093, 094	011	A	12	7	1		7	83
XIT Sand & Gravel, LLC	XIT S & G Pit	0418010	093, 094	014	A	21	7	7		7	90
Zack Burkett	Smith	0325205	093, 094	014	A	21	6	4		6	62

• Igneous Rocks

IGNEOUS											
Producer Information					Ratings						
Producer	Quarry	Producer Code	Product Code	Material Code	SAC	RSLA	RSSM			RSMID	CA-RSAI
							HMAC	ST	MS		
Cemex	McKelligon-Granite	2407206	093, 094	051	A	27	15	12		11	92
Cemex	Vado	0050310	093, 094	032	A	29	7	6		13	92
Colorado Materials	Davenport-Cline Basalt Quarry	1523215	093, 094	050	A	13	3	2		9	93
Granite Mountain Quarries	Plant 1	0050106	093, 094	051	A	29	3	1		5	92
Hanson Aggregates	Davis, OK	0050439	093, 094	032	A	17	9	9		9	94
Jobe Materials, L.P.	Padre Canyon	2411613	093, 094	051	A	30	11	1		11	92
Jobe Materials, L.P.	Vado Quarry	2450314	093, 094	032	A	29	11	9		13	95
Martin Marietta	Bird Hill	1523213	093, 094	050	A	15	12	11		11	95
Martin Marietta	Jones Mill	0050122	093, 094	040	A	17	3	3		6	96
Martin Marietta	Mill Creek (Grnt), OK	0050433	093, 094	051	A	22	2	2		8	98
Martin Marietta	Porcupine Mountain	0040105	093, 094	051	A	20	2	1		4	97
Martin Marietta	Snyder, OK	0050435	093, 094	051	A	25	2	2		5	100
Volcanic Stone	Cinder Mountain	0050313	093, 094	041	A	22	12	12		12	92
Vulcan Materials	Knippa	1523206	093, 094	050	A	12	8	6		14	93

• Lightweight

LIGHTWEIGHT													
Producer Information				Ratings									
Producer	Quarry	Producer Code	Material Code	SAC	RSLA	RSSM		RSMID	CA RSAI	Pressure Slake	Freeze/Thaw	Absorption	Density (pcf)
						HMAC	ST						
Trinity Expanded Shale and Clay	Streetman	1817502	048	A	28	7	8	29	99	HMAC 2.9 ST Gr 4, 3.5 ST Gr 3, 3.9	HMAC 6.6 ST Gr 4, 7.0 ST Gr 3, 8.1	11.5	52.6

